# SCALIX MULTIPURPOSE SCALES

# **UK Distributor**

**ATP Instrumentation Ltd** 

**Tournament Way** 

**Ivanhoe Industrial Estate** 

Ashby De La Zouch

Leicestershire

**LE65 2UU** 

Tel 01530 566800


Fax01530 560373

sales@atp-instruments.co.uk


www.atp-instrumentation.co.uk

# SCALIX PRECISION BALANCE FGL-600

# **INSTRUCTION MANUAL**



# **DESCRIPTION**



# **SPECIFICATIONS**

Model number	Capacity	Division
FGL -600	600g	0.01g
Platter	ф 115mm	
Net/gross weight	850/1500g	
	Standard carton: $32.5 \times 22.5 \times 11.5 \text{ (cm}^3\text{)}$	
Package		
Operating Temperature	0-40°C(32-104°F)	
	4 x AAA Size Batteries or	
Power source	AC/DC Power Adapter 9V/300mA	

# **FEATURES**

Kg, g, lb or oz Conversion

Auto Zero Tracking

Tare Facility

Large 15mm LCD

Auto Backlight LCD

**User Calibration** 

Plastic Protection Cover

Low Battery Indication

IMPORTANT; Remove batteries if using AC/DC Adaptor

## **CALIBRATION**

#### When and How to Calibrate the Scale

Calibration may be required when it is initially installed, if the scale is moved to a substantial distance.

This is necessary because the weight of a mass in one location is not necessarily the same in another location. Also, with time and use, mechanical deviations may occur.

#### How to calibrate

Press and hold the [MODE] key, then press and hold [ON/OFF] key. The display will then show [CAL] then show five digits.


Press [MODE] and the display will then flash [500g].

Place the calibrating weight on to the pan. Wait for the stable indicator to display, then press [MODE]. The display will show '-----' and then return to showing five numbers. Calibration is complete.


Press [ON/OFF] to turn the power off, Press [ON/OFF] to turn the power on again. Place 500g on the pan to check calibration. If it is not correct, repeat the calibration procedure.

## **PREPARATION**

#### **Installing Batteries/Connecting the AC/DC Adaptor**



#### AC/DC 300mA Power Adapter (optional)



Plug the AC/DC Adapter to the adapter socket on the side.

The AC input requirement could be 110,120,220,230 or 240Volts (50/60Hz) depending on the area where used, so please verify that the adaptor is correct

## 2. Setting up the scale/balance

#### **A** CAUTION

Avoid installing the scale/balance in direct sunlight that may cause discoloration or malfunctions. Place your scale/balance on a firm weighing table so that the scale/balance is level. (The scale/balance will not perform accurately when it is not level.)

Place the scale/balance on the firm surface that is flat and level for an accurate weighing.

#### **Before weighing**

Whenever possible, please allow the balance to warm up for 10 minutes after first turning the power on, so that the balance will function properly and accurately.

#### **Error messages**

EEEE: Overload Low battery

#### **Weighing Functions**

Press [ON/OFF] to turn on the scale. When the power is turned on the scale will go through a self-verification process and display all segments (8888) for a few seconds and then "0" will appear on the display. The scale is ready for use.

#### **Unit Weight Selection**

To select the weighing unit, press [UNIT] to select Kg or g or lb or oz. An indicator confirms the selected weight unit.

## **LCD Backlight**

Place the objects to be weighted onto the scale's pan. The weight is then displayed The scale has an **AUTO-BACKLIGHT** which activates when any weight is placed on the pan. It will automatically turn off if the scale is idle.

#### **Tare Facility**

If a container is to be used, place the container on to the pan. The scale will display the container's weight. Press [**ZERO**] and display will read zero. Place items in to the container and the displayed weight will be the contents only.

#### **Auto Power Off**

After approx. 3mins it can be user disabled.

Make sure the scale is switched off, press and hold down [TARE], then press [ON/OFF], whilst keeping [TARE] pressed, the display will show A\_ON or A OFF.

Press **[TARE]** to select A\_ON to activate power off function or A\_OFF to deactivate power off function.

Turn the scale off to save the change.

#### **Low Battery Indication**

If the power level falls below the required level then will be displayed. The batteries should then be changed. To continue weighing with this symbol displayed will result in non-accurate weighing.

#### IMPORTANT; Remove batteries if using AC/DC Adaptor